



382828



EAST ALTON, ILLINOIS 62024

RECEIVED

NOV 18 1984

ILL. E.P.A. - D.L.P.C.  
STATE OF ILLINOIS

September 19, 1984

## CERTIFIED MAIL

Mr. Eugene P. Theios, Manager  
Disposal Alternatives Unit  
Permit Section  
Division of Land Pollution Control  
Illinois Environmental Protection Agency  
2200 Churchill Road  
Springfield, Illinois 62706

Re: Supplemental Waste Stream Numbers: 811968, 820871, 820868

This is in response to your letter dated September 17, 1984, concerning three liquid hazardous waste streams generated at Olin Corporations' Main Plant Facility (1190200002) in East Alton, Illinois. These three hazardous waste streams contain free running liquid when they are generated from process operations. However, Olin physically treats each waste stream on-site which in turn leaves a residual solid waste that no longer contains free running liquid. To certify this fact, Olin has subjected representative samples of the three hazardous waste residuals to the "Paint Filter Test" as required by Section 729.320 of the Pollution Control Board's rules. Results of these tests indicated that no fluid portion of the samples dropped from the bottom of the paint filter after the specified five minute interval.

If there are any questions concerning this letter, please do not hesitate to contact me.

Very truly yours,

L. W. Maxson, Director  
Energy and Environmental Services

WJG/jso

cc: Mr. Gene Evans  
Brighton Landfill  
1201 Dunn Road  
St. Louis, MO 63138

RECEIVED

SEP 26 1984

IEPA-DLPC